

Annexure D

BUILDING SAFETY CERTIFICATE

No. 854 Dated: 14/06/2024

It is certified that the existing building K. B. Scholars School (name of the building or premises) at Pipli Road Ladwa (KBR) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>G+1</u>	—	—	—	—	—

The building is owned/occupied by Dr. S. C. Jindal, Director (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of S.D.P. P.W.D. B&R Ladwa (Name of Department/ Govt.) on 14/06/24 (date of inspection) in the presence of Dr. S. C. Jindal (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from for a period of years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on at by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : (Dharmvir)

Name : _____

Designation : _____

Name & Address of Department Office : _____

**Sub Divisional Engineer
Provincial Sub-Division
PWD (B&R) B/LADWA**